

May 22, 1997



Pete Wilson

Los Angeles Regional Water Quality Control Board Mr. Michael Young Integrated Environmental Services, Inc. 3990 Westerly Place, Suite 210 Newport Beach, CA 92660

101 Centre Plaza Drive Monterey Park, CA 91754-2156 (213) 266-7500 FAX (213) 266-7600

POST-REMEDIAL EXCAVATION CONFIRMATION SAMPLE REPORT, PARCEL A, REPORT No. 2 - McDONNELL DOUGLAS C-6 FACILITY - LOS ANGELES, CALIFORNIA (FILE NO. 100.315)

We have received and reviewed the Post Remedial Excavation Report for Parcel A, Report No. 2, at the McDonnell Douglas C-6 Facility in Los Angeles, dated May, 1997. The report presents the results of confirmation sampling conducted along the limits of the Building 37 excavation, and requests approval to backfill at this site. Based on the data presented in the report, we have no objection to the Building 37 excavation being backfilled, as requested.

If you have any questions or comments regarding the above, please contact me at (213) 266-7550.

J.E. ROSS, P.E., Unit Chief Site Cleanup Unit

CC:

Ms. Karen Baker, DTSC, Long Beach

Ms. Debbie Oudiz, Office of Scientific Affairs

Mr. Anand Rege, DTSC, Long Beach

Mr. Fred Strauss, Montgomery Watson, Inc.

Mr. John Johnson, Lockheed Martin

Mr. Jeff Dhont, Federal EPA

